

E.W. Howell Co., LLC

113 Crossways Park Drive

Woodbury, NY 11797

Phone: 516-921-7100

Fax: 516-921-7920

REQUEST FOR INFORMATION

No. 00036

TITLE: Missing Hardware

DATE: 1/4/2010

PROJECT: BNL CCWF-II

JOB:

TO: Attn: Alan Raphael
Brookhaven National Laboratory
Brookhaven Sciences Associates, LLC
Project Modernization Office
Upton, NY 11973-5000
Phone: 631-344-5854

STARTED:

COMPLETED:

REQUIRED: 1/11/2010

WORK

IMPACT: Unknown

SCHEDULE

IMPACT: Unknown

COST

IMPACT: Unknown

QUESTION:

1/4/2010

Missing Hardware

Drawing A-501 shows a double door for the recycle closet. This doorframe is not shown on the door schedule on drawing A-600. Please specify the hardware set.

CC: File, Bill Harrison

PROPOSED SOLUTION:

USE STAINLESS, OR WATER/MOISTURE RESISTENT
"STANDARD" DOOR HINGE, AND MAGNETIC
CATCHMENT. NO LOCK REQUIRED. NO DOOR
HANDLE REQUIRED.

ANSWER:

SEE ATTACHED PHOTO OF SIMILAR RECYCLE AREA
WITH PIANO HINGE ATTACHED DOOR.

SEE ATTACHED EXAMPLE
OF DOOR CATCH.



Requested By: E.W. Howell Co., LLC

Date: 1/11/2010

Signed: _____

Hans Laros





